



SERVICE BULLETIN

SB0013

Page 1 of 1

Cub Crafters, Inc. Considers Compliance Mandatory March 31, 2011

The parts of this Service Bulletin that change the Type Design of the aircraft have been approved by the FAA.

EFFECTIVE DATE: This SERVICE BULLETIN is effective **March 31, 2011.**

SUBJECT: MAGNETIC COMPASS DEVIATION

MODELS AFFECTED: CC18-180A SERIAL NUMBER 0001
CC18-180 SERIAL NUMBERS 0002 TO 0048

COMPLIANCE TIME: WITHIN NEXT 50 HOURS OR AT ANNUAL, WHICHEVER COMES FIRST.

PURPOSE: Cub Crafters has determined that on certain aircraft, the deviations of the magnetic compass may be greater than 10 degrees when the landing/taxi lights or the pitot heat are turned on. When the aircraft was delivered by Cub Crafters, the compass was calibrated with the landing/taxi lights and the pitot heat off. The compass card included with the aircraft when it was delivered showed the deviations with the landing/taxi lights and the pitot heat turned off. (Note that the landing and taxi lights are operated by a single switch.)

PARTS LIST:

<u>PART</u>	<u>DESCRIPTION</u>	<u>QTY</u>
TC9356-001	Compass Deviation Placard	1

INSTRUCTIONS:

1. Install TC9356-001 (Compass Deviation Placard) as close to the compass correction card on the instrument panel, as possible.
2. Make appropriate entry in aircraft log books.

If you are no longer in possession of this aircraft, please forward this information to the present owner/operator and notify Cub Crafters, Inc. of the address of the current owner to:

Cub Crafters, Inc.
1918 South 16th Avenue
Yakima, WA 98903-1212
1-877-484-7865 or 1-509-248-9491
support@cubcrafters.com

Please include the aircraft registration number, serial number, current name, and address of the owner and/or operator.